UNIVERSITY OF CAMBRIDGE INTERNATIONAL EXAMINATIONS International General Certificate of Secondary Education

www.papacambridge.com MARK SCHEME for the May/June 2007 guestion paper

0445 DESIGN AND TECHNOLOGY

0445/04

Paper 4 (Systems and Control), maximum raw mark 50


This mark scheme is published as an aid to teachers and candidates, to indicate the requirements of the examination. It shows the basis on which Examiners were instructed to award marks. It does not indicate the details of the discussions that took place at an Examiners' meeting before marking began.

All Examiners are instructed that alternative correct answers and unexpected approaches in candidates' scripts must be given marks that fairly reflect the relevant knowledge and skills demonstrated.


Mark schemes must be read in conjunction with the question papers and the report on the examination.

CIE will not enter into discussions or correspondence in connection with these mark schemes.

CIE is publishing the mark schemes for the May/June 2007 question papers for most IGCSE, GCE Advanced Level and Advanced Subsidiary Level syllabuses and some Ordinary Level syllabuses.




7



[3]


[2]

8 A member (1) that experiences compressive load (1)



Section B


11 (a)



[4]


(b) Interface (1) between two circuits of differing current rating (1).
Control of large current by small current device (1).

[3]



[3]


- (e) (i) Adjusts the sensitivity of the circuit (1) by varying its resistance (1) and thus the bias voltage and base current flowing (1). [2]
 - (ii) A clamping diode is used to reduce the possibility of damage to the I C (1) from back emf (1) generated by the relay coil (1). [2]




(U)	2	Shell construction (1) plus example (1)	[2]
(c)	Dia	bracing (1) gram showing cross bracing (2) propriate labelling (1)	[4]


(d)	Clear diagram showing the cutting effect of shear force (2)	
	Appropriate label (1)	[3]

- (e) (i) This increases the rigidity (1) of the casing at its edges thus reducing the chances of buckling (1) or failure under load (1). [2]
 - (ii) Help to evenly distribute the stresses (1) in the casing thus reducing the chances of stress fracture (1) or stress build up (1). [2]
 - (iii) DTI gauge [1]





- (e) Fig.10 shows part of the starting system for a cement mixer.
 - (i)



[2]

[3]

- (ii) X Driver[1]Y Driven[1]
- (iii) VR = Teeth on driven / teeth on driver (1) VR = 56 / 14 (1) VR = 4 : 1 (1)
- (f) (i) Gives the user greater MA (1) thus makes the effort needed less (1) and the handle easier to turn (1) [2]